




## Dry Contact Adapter for CIE-H14 (DCA) V1.0

- This Dry Contact Adapter (DCA) supplies a function to change CIE-H14's digital input ports to dry contact interface (relay or switch).

	Without DCA	With DCA
Input Condition	1: over DC1.8V between the input ports 0: under DC1.5V between the input ports	1: two ports are short 0: two ports are open
Diagram		
Adaptable devices	Devices or sensors which output DC voltage	Relays or Switches

### • DCA's Interface



Acceptable input resistance	
Input Power	Acceptable resistance between two ports
8.5V	2KΩ
12V	5KΩ
24V	17KΩ
38V	31KΩ

- **Examples**

